

Trek Bicycle Corporation (Australia) Pty Ltd—SR Suntour SF11 XCM-V3 Fork

PRA number: 2012/13193

Date created: 1st July 2012



Product information

Product description

Mountain bicycle suspension fork that may have been installed on the bicycles identified below.

Identifying features

SR Suntour Suspension Fork - Date Codes: CK110301 through CK110731

Affected brand: Trek

Model year: 2012

Model name: 3900 Disc

What are the hazards?

If the suspension fork's internal support tubes break during use, the rider may lose control and crash.

What are the defects?

The suspension fork's internal support tubes may break.

Dates available for sale

★ 1st June 2011 - 30th June 2012

Where the product was sold

★ Nationally

Traders who sold this product

Trek bicycle retailers

Supplier

Trek Bicycle Corporation (Australia) Pty Ltd

Supplier's web site

<http://trekbikes.com/au/en>

What should consumers do?

Consumers should immediately stop using bicycles with these forks and return the bicycles to any authorised Trek dealer for a free repair.